Maryland Historical Trust

Maryland Inventory of Historic Properties number:	<u>M</u> .	-5	19	A				
Name: MD Sover Chuic	<u>h</u>	<u> </u>	ree	De	٧			
The bridge referenced herein was inventoried by the Maryla Historic Bridge Inventory, and SHA provided the Trust with The Trust accepted the Historic Bridge Inventory on April 3 determination of eligibility.	h elig	ibility	detern	ninatio	ons in	Febru	arv 2	001.
MARYLAND HISTOR	ICA	LTRU	JST					
Eligibility RecommendedX	ommended X Eligibility Not Recommended Eligibility Not Recommended None A B C D Considerations: A B C D E F G None							
Criteria:AB X_CD Considerations:	_A _	B _	_c _	_D _	_E_	F _	_G	None
Comments:								
								
Reviewer, OPS:_Anne E. Bruder Date:3 April 2001								
Reviewer, OPS:_Anne E. Bruder			Date	e:3 .	April :	2001_		

A^e~

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust

MHT Number SM-519

Name and SHA No. 18010 over Church Creek

Location: Street/Road Name and Number: MD 5 over Church Creek
City/Town: Church Cove Vicinity X
County: St. Mary's
Ownership: X State County Municipal Other
This bridge projects over:RoadRailway_X_WaterLand
Is the bridge located within a designated district: yes X no
NR listed districtNR determined eligible districtlocally designatedother Name of District
Bridge Type:
Timber BridgeBeam BridgeTruss-CoveredTrestleTimber-and-Concrete
_Stone Arch
Metal Truss
Movable BridgeSwingBascule Single Leaf_Bascule Multiple LeafVertical Lift_Retractile_Pontoon
X_Metal Girder _X_Rolled GirderRolled Girder Concrete Encased _Plate GirderPlate Girder Concrete Encased
_Metal Suspension
Metal Arch

_Meta	l Cantilever
_Conc	rete
	_Concrete Arch _Concrete Slab_Concrete Beam
	_Rigid Frame
	_Other Type Name

Description:

Describe Setting:

Bridge No. 18010 carries MD 5 north-south over Church Creek in St. Mary's County, Maryland. The north approach is curved and descends to the bridge. The south approach is straight and descends to the bridge. The approaches and areas to the east and west of the bridge are heavily wooded. Overhead lines are visible on both sides of the bridge.

Describe Superstructure and Substructure:

The structure is a steel beam bridge 23' in length with a clear roadway width of 30'. The substructure consists of two concrete abutments and wingwalls. The bridge deck is reinforced concrete with a bituminous wearing surface overlay.

In May 1983, deterioration of the bridge included misalignment of the wingwalls at the construction joints. The top northeast wingwall exhibited spalling, and the beams were rusting throughout.

Discuss Major Alterations:

In 1985 the handrail was removed and a guardrail was installed. There are no other records of modifications to this bridge.

History:

When Built: 1936

Why Built: Local transportation needs

Who Built: Unknown

Why Altered: Not Applicable

Was this bridge built as part of an organized bridge building campaign: Yes

Surveyor Analysis:

This bridge may have NR significance for association with:

_A Events _Person

x C Engineering/Architectural

Was this bridge constructed in response to significant events in Maryland or local history:

No, this bridge was not constructed in response to significant events in Maryland or local history.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

No, the construction and/or alteration of this bridge has had no significant impact on the growth and development of the area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district?

No, this bridge is not located in an area which may be eligible for historic designation.

Is the bridge a significant example of its type?

This bridge may be a significant example of its type.

Does the bridge retain integrity of the important elements described in the Context Addendum?

Yes, this bridge appear to retain the integrity of its primary character defining elements.

Should this bridge be given further study before significance analysis is made and Why?

No further study of this bridge is warranted. This bridge appears to retain its integrity as defined by the Context Addendum. This bridge may be eligible for inclusion on the National Register of Historic Places.

Bibliography:

Greiner, Inc.

1995 Maryland Inventory of Historic Bridges.

Spero, P.A.C. & Company, and Louis Berger & Associates

1994 Historic Bridges in Maryland: Historic Bridge Context.

State Highway Administration

v.d. Bridge Inspection files.

United States Geological Survey

1987 7.5' St. Mary's City Quadrangle.


United States Geological Survey

1912 15' Point Lookout Quadrangle.

Surveyor:

Name: Jason D. Moser Date: September 1995

Organization: State Highway Admin. Telephone: (410) 321-2213 Address: 2323 West Joppa Road Brooklandville, MD 21022





SM-519 ST MARYS COUNTY D. BHOUMICE 2-1-95 MARYLAND SHPO MD 5 OVER CHURCH CREEK LOOKING NORTH ON MO 5 (BRIDGE 13010)



200 4 5/11-5/9 ST MARYS COUNTY D. BHAUMIE 2-1-95 MARY CAND SHPO MD 5 OVER CHURCH CREEK LOOKING WEST (UPSTREAM FACE) (BRIDGE 15010)



3 OF 4 SM-519 ST MARYS COUNTY D. BHOUMK 2-1-95 4-3 MARYLAND SHPO MDS OVER CHURCH CREER LODICING SOUTH ON MD 5 (BRIDGE 18010)



4 OF 4 5111-519 ST MARYS COUNTY D. BHAUMIK 2-1-95 SHA MARYLAND SHPO MD 5 OVER CHURCH CREEK COOKING EAST COUNSTREAM FACE) (BRIDGE 18010)